aie :	0127Z 29 NOV 60	10P SECRET	1 A/C/OP	5 Intel	
	DIRECTOR	Participate de Calabara de Labora de Maria de Calabara		Ri	
: MO	DPD (1,2,3,4,5,6,7,8,9,10)		GM2. 30		
TION:				Committee of the commit	
info :	C/C (11) Decument No.		ROUTINE	ROUTINE	
	VP	CLASS, Lifering TO: TS (S) (	25X1A	STILL STATE OF THE	
	TOR: 0218Z 29 NOV 50	AUTH: HR To-2	-26K	IN 37819	
or <del>iz</del> anda O	and the state of t	DATE : 48 Aug 86 REVIEWER	25X1A cite	017	
	CREEN EVES				
	FOR COL BEERLI FROM S				
	1. FROM INFO AVAI	LABLE AT THIS TIME AM	DISAPPOINTED	IN	
	RESULTS OBTAINED ON THE FIRST SORTIE. STANDARD PROCEDURES				
	WERE FOLLOWED AND DO NOT BELIEVE DIFFICULTIES CAN BE ATTRIBUTED				
	TO FAULTY MAINTENANCE, HOWEVER, THIS SORTIE HAS BEEN THOROUGHLY				
	REVIEWED WITH ALL PERSONNEL CONCERNED AND EVERY EFFORT IS BEING				
	MADE TO INSURE OPTIMUM RESULTS.				
	2. CONSIDERABLE DIFFICULTY WAS ENCOUNTERED ON 25 25X1A				
		PREPARATION FOR MISS		VAL. 2	
5X1 <i>F</i>	26 WAS FINALLY	MADE OPERATIONAL PRIC	OR TO DEPARTUR	E BUT	
	THE SLAVE RECORDER MALFUNCTIONED DURING FLIGHT WHICH RESULTED				
	IN THE LOSS OF X AND	P BANDS. S AND L BANI	DS ARE BELIEVE	D	
	TO BE SATISFACTORY. DUE TO EXCESSIVE TIME CONSUMED ON PREFLIGHT				
	OF THIS SYSTEM MAINTENANCE PERSONNEL WERE UNABLE TO COMPLETELY				
	CORRECT A MALFUNCTION IN THE FOUR HUNDRED CYCLE POWER OF 25X				
	8. BOTH OF THESE SYSTEMS ARE NOW IN COMMISSION, HOWEVER, HAVE				
	NOT BEEN SATISFIED WI				
		r Reid AP 2002 PM 24 CIA-RDI	16. The state of t	- / /	
	· · · · · · · · · · · · · · · · · · ·	HER THAN THE ISSUING OFFICE	1	opy No.	

<b>x</b> :	Approved for Release 2002/08/21 CIA-RIP8950569R000300030086-2			
25X1A	017 (IN 37819) PAGE TWO			
25X1A	3. WE DO NOT KNOW AT THIS TIME IF ALL OF THE TAKE FROM THE  3 WAS AFFECTED BY THE MALFUNCTION OF THE VACUUM SOLONOID  BUT HAVE BEEN ASSURED THAT IT WAS FUNCTIONING PROPERLY AT			
	TAKE OFF.			
	4. PROPOSE TO UTILIZE ARTICLE 353 ON THE NEXT SORTIE EVEN			
25X1A	THOUGH IT DOES NOT HAVE A 26 CAPABILITY. BELIEVE THAT /			
25X1A	THE ADVANTAGE OF IMPROVED 3 FROM THE MORE STABLE PLATFORM			
25X1A 25X1A	WILL OFFSET DISADVANTAGE OF LOSS OF26. THE26			
207(17(	CAN THEN BE USED ON SUBSEQUENT FLIGHTS AS REQUIRED.			
	5. AM CONFIDENT THAT YOU MAY EXPECT CONSIDERABLE IMPROVEMENT			
	ON FUTURE SORTIES.			

END OF MESSAGE